	Property is: Single Far	nily 🗹	Duplex	□ Other □	
Date:	10/1/2015	, _	2 0,010		
Below is the I		ealth and s	afety issue:	s. The City of Milwaukee, the Redevelopment A	Authority, and their representatives
ake no respo	onsibility for problems discovered	after the ins	spection da	te, or for omissions through error or oversight.  deral Block Grant or HOME programs.	•
		inpanies, oi	by the rec	ierai block Grant of Flowic programs.	
	Condition Report				
_ocation Site	Required Work Landscaping	n/a □	Yes ✓	Note/Comments seed yard where cars are parked	Cost \$ 500.00
	Landscaping	n/a $\square$	Yes 🗸	cut trees back from foundation	\$ 625.00
	Service walks	n/a 🗌	Yes 🗸		\$ 900.00
	Fencing	n/a ✓	Yes		\$
	Parking	n/a ✓	Yes		\$
	Retaining walls	n/a ✓	Yes 🗌		\$
	Other	n/a $\square$	Yes		\$
	Other	n/a $\square$	Yes		\$ \$
Garage	Olio	11/4	103		·
	Singles: repair	n/a ✓	Yes 🗌		\$
	Shingles: Roof over existing	n/a ✓	Yes 🗌		\$
	Shingles:Tear off & re-roof	n/a	Yes ✓		\$ 4,360.00
	Gutters/downspouts	n/a ✓	Yes 🗌		\$
	Flashing	n/a ✓	Yes		\$
	Eaves	n/a	Yes 🗸		\$ 450.00
	Siding	n/a ✓	Yes 🗌		\$
	Doors	n/a	Yes 🗸		\$ 600.00
	Windows	n/a ✓	Yes 🗌		\$
	Slab	n/a ✓	Yes 🗌		\$
	Paint	n/a	Yes 🗸	wood surfaces	\$ 1,900.00
	Electrical	n/a	Yes 🗸		\$ 250.00
	Other	n/a	Yes 🗌		\$
Porches	Roof	n/a ☑	Yes 🗌		\$
	Deck-front	n/a 🗌	Yes 🗸	hand/guardrails	\$ 625.00
	Deckrear	n/a $\square$	Yes 🗸	repair	\$ 250.00
	Steps/handrails	n/a ✓	Yes	- Opan	\$
	Ceiling	n/a ✓	Yes 🗌		\$
	Guardrails	n/a ✓	Yes 🗌		\$
	Structural	n/a ✓	Yes [		\$ \$
	Paint	n/a 📙	Yes 🗸		\$ 600.00

n/a 🗌 Yes 🗌

Other

\$

## House

Chimney	n/a ☐ Yes ☑	\$ 1,100.00
Shingles: repair	n/a ☐ Yes ☑	\$ 850.00
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$ 
Shingles:Tear off & re-roof	n/a ☑ Yes 🗌	\$ 
Gutters/downspouts	n/a ☑ Yes 🗌	\$ 
Flashing	n/a ☑ Yes 🗌	\$ 
Eaves	n/a ☑ Yes 🗌	\$ 
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ☑ Yes 🗌	\$ 
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 700.00
Storm Windows	n/a ☑ Yes 🗌	\$ 
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 620.00
Paint	n/a  Yes  previously painted surfaces	\$ 2,600.00
Foundation	n/a ☑ Yes 🗌	\$ 
Electrical	n/a ☑ Yes □	\$ 
Other	n/a  Yes  window screens	\$ 350.00
Other	n/a 🗌 Yes 🗌	\$ 
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$ 

Exterior: Estimated Cost:\* \$

\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

17,280.00

Interior Co	ondition Report Unit: Entire unit (single family)	<b>V</b>				Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work					Other   Other	
rieating	Repair/replace boiler	n/a [	<b>⊘</b> Y	es [			\$
	Repair radiation	n/a [	✓ Y	es [			\$
	Repair/replace furnace	n/a	_ Y	es [	<b>√</b>	assumed-no basement access	\$ 3,080.00
	Repair ductwork	n/a	Y	es [	J	assumed	\$ 400.00
	Replace thermostat	n/a [	Y	es [	<b>√</b>	assumed-any existing furnace not operational	\$ 100.00
	Repair/replace grilles	n/a [	✓ Y	es [			\$
Electrical	Tune boiler/furn. insp ht exchang	n/a	∕ Y	es [			\$
Liectrical	Repair/replace receptacles	n/a	Y	es [	<b>√</b>		\$ 800.00
	Repair/replace switches	n/a	_ Y	es [	<b>√</b>		\$ 800.00
	Repair/replace fixtures	n/a	_ Y	es [	<b>√</b>		\$ 800.00
	Install outlets and circuits	n/a [	✓ Y	es [			\$ 
	Install outlets and circuits	n/a [	✓ Y	es [			\$ 
	Install outlets and circuits	n/a [	✓ Y	es [			\$
	Install outlets and circuits	n/a [	✓ Y	es [			\$
	Upgrade service	n/a [	✓ Y	es [			\$
	Other	n/a	Y	es [	<b>√</b>	permit	\$ 85.00
	Other	n/a	_ Y	es [			\$
Plumbing	Repair/replace kitchen sink	n/a [	✓ Y	es [			\$
	Repair/replace kitchen sink fauce	n/a [	✓ Y	es [			\$
	Repair/replace tub	n/a [	✓ Y	es [			\$
	Repair/replace tub faucet	n/a [	✓ Y	es [			\$
	Repair/replace toilet	n/a [	✓ Y	es [			\$
	Repair/replace lavatory	n/a	_ Y	es [	<b>√</b>		\$ 275.00
	Repair/replace lavatory faucet	n/a [	✓ Y	es [			\$ 
	Repair/replace wash tub	n/a	/ Y	es [			\$ 
	Repair/replace wash tub faucet	n/a	✓ Y	es [			\$
	Unclog piping:	n/a [	✓ Y	es [			\$
	Repair drain/waste/vent piping	n/a	_ Y	es [	<b>√</b>		\$ 240.00
	Repair water piping	n/a	Y	es [			\$
	Repair/replace water heater	n/a	Y	es [	<b>√</b>	assumed-no basement access	\$ 1,300.00
	Other	n/a	_ Y	es [			\$

n/a ☐ Yes ☐ \$

Other

Windows							
	Replace broken glass	n/a	<b>V</b>	Yes			\$
	Repair or replace sash	n/a	<b>V</b>	Yes			\$
Doors							
	Repair or replace doors	n/a		Yes	J		\$ 760.00
	Repair or repl. locks/latches	n/a		Yes	<b>✓</b>	Self Help	\$ 220.00
Walls/Ceiling	gs						
	Repair or repl. @ defective	n/a		Yes	J		\$ 2,200.00
Paint							
	Repair or repl. @ defective	n/a		Yes	<b>✓</b>		\$ 1,100.00
Fire Safety							
•	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>V</b>	Self Help	\$ 55.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>V</b>	Self Help	\$ 165.00
	Install smoke/CO alarm: 2nd flr.	n/a	<b>V</b>	Yes		Self Help	\$ 
Handrails	5 1/ 1 1/ 1	,	_	.,	_		0.40.00
Stairs	Repair/replace defective	n/a		Yes	✓	basement-assumed, no access	\$ 248.00
Stall's	Repair defective	n/a		Yes	<b>V</b>	basement-assumed, no access	\$ 864.00
Floors					_		
Other	Repair defective	n/a		Yes	1		\$ 2,700.00
Other		n/a		Yes			\$
		n/a		Yes			\$
		n/a		Yes			\$
		n/a		Yes			\$
						Interior: Estimated Cost:	\$ 16,192.00
						Total Exterior and Interior Cost:*	\$ 33,472.00

Inspected by: Tom Frank Date: 9/30/15

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

 $<sup>\</sup>ensuremath{^{\star}}\xspace$  average contracted cost. Actual costs may vary. Self help will reduce the amount.